## **PURCHASE ORDER**

## Department of Social Welfare and Development Field Office VII

cor. MJ Cuenco Ave. & Gen. Maxilom Ave. ,Cebu City Tel. # 2330261, 2338785 Fax # 4129908, 2321192

Supplier:

7th DCNC WORLDWIDE INC.

Address:

A.C. Cortes Ave., Mandaue City

Contact No.:

(032)514-8621

Contact Person: Benerlie B. Abaquita

PO No.

DSWD7-18-639

Date:

10/03/2018

Small Value

Procurement

484-755-873-000

Mode of Procurement:

Gentlemen:

furnish this Office the following articles subject to the terms and conditions contained he

Place of Delivery:  Date of Delivery:		DSWD FO 7, Cebu City	Delivery Term: Payment Term:		upon receipt of approved P.O.  within 30 calendar days after complete delivery & receipt of billing.
1	lot	Provision of labor and materials for the Check- up/Repair, Installation, Reprocessing, and General cleaning and commissioning of six (6) Airconditioning units at DSWD FOVII with the following details:			83,000.00
		<ol> <li>CARRIER (3TR) Floor Mounted Location : Pantawid Office Model no. : ASBFM36OBA         <ul> <li>Replacement of busted Compressor</li> <li>Replacement of Running Dual Capacitor (60μF/460VAC)</li> <li>Replacement of indoor Fan Capacitor (5μF/460VAC)</li> <li>Replacement of Drier Filter Element</li> <li>Charging of refrigerant to the whole system</li> <li>Supply and Installation of other accessories needed for the proper functionality of the unit.</li> </ul> </li> </ol>		5%	3,705.36
		2. CARRIER Floor Mounted Location: Social Marketing Section Model no.: 38ASB360BA - Replacement of Starting Capacitor (60µF/430VAC) - Replacement of broken Fan Blade - Replacement of Rubber mounting for fan motor -Supply and Installation of other accessories needed for the proper functionality of the unit.		1%	741.07
		3. 2-3TR Units Floor Mounted (KOPPEL & DAIKIN) Location: Accounting Section - Remove old sub-standard rubber insulation and install new standard material (1/2" x 5/8" & 3/8 x 1/2") -Reorganize the tubing line & 5/8 copper, leak testing of brazed joints and recommissioning of the unit -Supply and Installation of other accessories needed for the proper functionality of the unit.		Total after tax	78,553.5

Stock No.	Unit	Desciption	Quantity	Unit Cost	Amount
2009	efested us	4. KOPPEL (3TR) Floor Mounted			
.Delation		Location : ARRS Section			
1946年第	1436 15 sal	- Verification of possible leaks of the tubing joint			
		between high & low line, flushing the line with N2,			
	2012/15/2012	charging of refrigerant to the correct pressure			
		level to the whole system between high & low side			
		- Testing and commissioning including the			
		performance test of the compressor and			
		evaporator			
		-Supply and Installation of other accessories	SV REALING		
		needed for the proper functionality of the unit.	Mest Literature		Tay I was a
		was recorded an array reaches the regions, and tableliles have a larger and the recommen			
		E KODDEL Calling mounted	Control State of the	matterials of the sure	Marianga, 11 Destantan
	15	5. KOPPEL Ceiling mounted Location: ICTS Server room	The street of	EL BOOM WITH THE AT AN	and the line
		- Dismantle the fan blade motor from the	Lifety Bulletin	The state of the s	
		compressor compartment	rajous erait	san na hain Kuta B	TOTAL CO.
	19-7	- Remove the broken fan blade	and the same	e.) – e. linga eina finalis	na andr
		- Dismantle the fan blade motor and install new	an bertaelt	u dagina (etroano	A PARTY OF THE PAR
		bearing	16 57 36 4	ve traile ent his	A Lucianian
		- Installation of the new motor bearing and the	and on light	Page 1964 Carlot Carlot	A STATE OF THE STA
		new fan blade	land and an in	to be "advantage overly overly	d toping the
	R-13	- Check for correct alignment, wiring and		pilian polypas sei	Labiah sa
	18	verification if the fan blade motor is free and	Carrie 103 to	April 1991 Production	apod Billio
		smooth while turning manually without power	day sail mit	CARREST DISSESSED	en for har
	10513	- Energize the unit and check fan blade motor is	gardine maga	ed term er til bit	Applications of the second
	1 4	rotating normally	0 10 10 10	A STANDARD BY A STANDARD	SERVICE TO
	10861	- Observe for noise sound, rectify if found any			world Books
		-Supply and Installation of other accessories	Rand Control of	ensellingen stelle in	olleconnel
		needed for the proper functionality of the unit.			
	v manus	the set for senting a strate of the DS Voltaged School off of the	ing property	erto en Nague y 4 au	5) At database
	10.0	6. Supply of Running capacitors	DWG DWW	Earn, minutes, respinga	An e popul
		- 3 pcs 60µF/450VAC (single capacitor)	and the second	or one thinks because die	Basic Loss III
		- 3 pcs 60µF/460VAC (single capacitor)		e main a management	a state and
		- 3 pcs 60µF/450VAC (dual capacitor)			
		- 3 pcs 60µF/460VAC (dual capacitor)	ed to unique	e alia agriculturali da	County (1)
		And the second facility in the measurement and the second facility is a second facility of the second secon	250 154	All reall y a Linuxer of	and the same
		Note: Technician must be at least NCII certified	The same state of	10 High 2 to 17 W	38 (24)(19) (19)
		2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		to the characters of	ognesian A persented
		Purpose:	or to success	orther reloader of	h taken
		Purpose: for repairs and maintenance of		programme and the same of	Label A 12
		Airconditioning units at FOVII	The same of	A 200 (St. 10-35) (000) 23	1100
	2.00	(Ref: PR No.: DSWD7-18-0888)	AU HORAL	nozwali of notitie	CANSON IN THE
(Total Amount in		Seventy eight thousand five hundred fifty three pesos and 57/100	1000 03 000	Nett of tax	78,553.5
In case of fail	ure to ma	ke the full delivery within the time specified above, a penalty of	one-tenth (1/	10)	
		ay of delay shall be imposed.			
			Very truly	voure -	
			very truly	A	11/
		and perform the engine of the		200000	Libonic
Conforme:	0.1	5/10- 7		GRACE Q S	
	Dela	Some ill		OIC- ARD for A	dministration
	Signati	re over Printed Name of Supplier			6.
	Olgitall	An Anna contract			
		$\vee$			
		10/2 /10			
		Date			
		/Date/			
unds Available:		A	AL	OBS No. :	
		[N			
		LOUIE RAYO VILLARIN CPA	II An	nount :	
		LOUIE RAY C. VILLARIN, CPA Regional Accountant	An	nount :	

AO 6/15/02 PO No. DSWD7 18-639